Supplement

Manual Title: Auxiliary Input Adapter for 17xx Instruction Part Number: 4749275 Supplement Issue: December 2015 Issue Date: Print Date: 7/17 1, 1/17 Page Count: Revision/Date: 1

This supplement contains information necessary to ensure the accuracy of the above manual.



Change #1, 473

In the Accuracy table replace the Voltage Divider Input row with:

Voltage Divider Input	±1000 V	±(0.7 % + 0.02 %)
-----------------------	---------	-------------------

Following the **Accuracy** table replace the **Additional Error**s table with:

Additional Errors:

Influence by galvanic connection of sources

	Typical additional errors for measurements on galvanic				
	connected sources				
	2x Divider			2x Direct	
	Inputs	Divider Input / Direct Input		Inputs	
	AUX1 &	AUX1 or	AUX1 or	AUX1 &	
	AUX2	AUX2	AUX2	AUX2	
	1000V	1000V	max 30V to	max 30V to	
Type of	CATIII	CATIII	ground	ground	
Influence	Input	Input	Input	Input	
Common	1.5 % of		30 ppm of	0.15 % of	
Mode [1]	V _{CM}	3 % of V _{CM}	V _{CM}	V_{CM}	
Voltage	0.7 % of	1.5 % of	15 ppm of	0.15 % of	
difference [2]	V_{diff}	V_{diff}	V_{diff}	V_{diff}	

^[1] Common Mode Voltage V_{CM} = Voltage difference between LO potentials of AUX1 and AUX2

7/17 1

^[2] Voltage difference V_{diff} = difference of voltages V_{AUX1} - V_{AUX2} with connected LO potential